

**To:** Breffle, Don[Breffle.Don@epa.gov]  
**From:** Rodrigo Jurado  
**Sent:** Mon 1/26/2015 7:25:36 PM  
**Subject:** Petroglyph's Ute Tribal 05-08 Injector

Mr. Breffle,

As we discussed previously, Petroglyph Operating plans to work-over and re-perforate the Ute Tribal 05-08 Injector. At this time a decision has not been made as to whether existing perforations will be acidized or not; but here is our tentative work-over plan:

Petroglyph Operating plans to work-over and re-perforate the referenced well. We plan to pull all tubing and packers, scan log on the way out, lay down all bad pipe, make a bit and scraper run to PBTD, circulate the well and re-perforate at the following depths: 5474-87, 5458-64, 5443-48, 5436-40, 5410-16, 5398-5403 & 5359-66. New perforations will be made at: 5292-5300, 4920-22, 4313-17, 4926-34, 4764-72, 4498-4504, 4490-93 & 4480-88. We will break down perfs, test their injection rates, run in with an Arrowset 1 Packer and perform a Mechanical Integrity Test. Injection will resume after EPA Approval is received.

Equipment has been moved on location and work is underway. We will submit a detailed subsequent report to you, along with a Mechanical Integrity Test as soon as work is completed and data is gathered.

Thanks,

Rodrigo Jurado

Petroglyph Operating Company, Inc.

Regulatory Compliance Specialist

P.O. BOX 607

Roosevelt, UT 84066

OFFICE: (435) 722-5302

MOBILE: (435) 609-3239

FAX: (435) 722-9145

attachments is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender immediately and destroy all copies of the communication and any attachments.